


THREE PHASE TRANSFORMER



| Power (VA) | MAX DIMENSIONS (mm) | | | | | Weight (kg) |
|------------|---------------------|-----|-----|-----|-----|-------------|
| | A | B | C | D | E | |
| 500 | 180 | 180 | 85 | 150 | 65 | * |
| 1000 | 180 | 180 | 105 | 150 | 85 | 9,7 |
| 1600 | 240 | 230 | 120 | 200 | 85 | 14,3 |
| 2000 | 240 | 230 | 125 | 200 | 95 | 18,2 |
| 2500 | 240 | 230 | 135 | 200 | 105 | 20,9 |
| 3000 | 240 | 230 | 150 | 200 | 120 | 24 |
| 4000 | 300 | 305 | 130 | 250 | 90 | 28,4 |
| 5000 | 300 | 305 | 140 | 250 | 100 | 33 |
| 6300 | 300 | 305 | 160 | 250 | 120 | 48 |
| 8000 | 360 | 350 | 140 | 325 | 120 | 58 |
| 10000 | 360 | 350 | 160 | 325 | 140 | 63 |
| 12000 | 420 | 405 | 205 | 370 | 140 | 85,3 |
| 16000 | 420 | 405 | 205 | 370 | 150 | 101,9 |
| 20000 | 480 | 470 | 205 | 425 | 170 | 130 |
| 25000 | 480 | 470 | 245 | 425 | 210 | 178,3 |